Quality Control

Thursday, November 28, 2013 3:17:24 PM Item ID: D3265-043 Accept *N900040100* Setup Start **Revision ID:** Item Name: Rib Assembly **Start Date:** 11/28/2013 Start Qty: 1.00 **Cust Item ID:** Required Date: 12/5/2013 Req'd Qty: 1.00 *1* **Customer:** Reference: Run Process Plan: MV-Date: \3-(1-28) Tooling: Approvals: Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number Stamp Draw Nbr **Revision Nbr** D3265 Е Weld per dwg A/R S.S. rod Batch: 0.00 Large Fab *100* 1123823 13-11-28 Large Fab 0.00 Memo Large Fab 1- Cut D3265-7 as per dwg 2- Drill holes and c'sink them as per dwg using DT9814 3- Deburr and remove identification markings on tube QC10- Inspect visual per OSI004- ground welds 0.00 13.11.28 1* *105* OC : 0.00 Memo Quality Control QC6- Inspect dimensions to drawing 0.00 13.11.28 /* *110*

0.00

Memo

DQA:	Date:														
						WORK ORDER NON	-CC	ONFO	RMANCE / U	PDATE				<i>مانگ</i> A E	ROSPACE
QA Closed:			Date:								Wo	rk Order up	date only		
Work Orde	or.					DISPOSITION									
						Rework		Skid-tube	Crosstube			Water Jet	Engine	ering	
Part N	lo.					Scrap	1		Machining	Small Fab				⊣ `	iality
						Use-as-is	1		noforming	Finishing	\dashv		re/Packaging	⊣	ther
NCR N	۱o.					Suspected Unapproved	1		Large Fab	Composite	_		Supplier	1	
	•												<u>. </u>	_	
Root					Desci	ription of work order update		nitial	Act	ion		Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Desci	ription		Date	Verification	QC In	spector
Design															
Doc/Data															
Equip/Tooling															
Handling/Pre															
Material		_					ĺ								
Operator						f							₹.		
Offset/Setup		_													
Process													,		
Supplier													·.		
Training						:	1				- 1				
Transport	<u> </u>	ļ	ŀ		ŀ										
Unapproved			<u> </u>												
							FA	ULT CA	TEGORY						
Landi	_	1			_	General	_	1		1				٦	
	<u> </u>	Bending			<u> </u>	Bend	\vdash	1	Program		-	Outside Dim		Pressure/	Forced
	<u> </u>	Centre No	ot Concer	ntric	<u> </u>	BOM/Route	<u> </u>	Grain			\vdash	Over/Under	-	Set-up	
	_	Cracks		_	<u> </u>	Broken/Damage/Defect	_	Hardwa			\vdash	Part Incorred	<u> </u>	Temperat	ure/Cure
	<u> </u>	Crimp/Kir	nk/Ripple	/Wave	_	Burrs	ļ	- I	ion Incomplete/U	·	_	Part Lost/Mi	ssing	Weld	
	<u> </u>	Cuffs			<u> </u>	Contamination	<u></u>	4	tions Incomplete/I	Jnclear	—	Part Moved	L	Wrong Sto	ock Pulled
	<u> </u>	Crushing			<u> </u>	Countersink	\vdash	•	gned/off center		-	Positioned V		٦	
	_	Heat Trea			<u> </u>	Cut Too Short	\vdash	Mislabe			Ш	Power Loss/	Surge	Other	
	Inspection Strip in Tube					Drawing	\vdash	Misrea			-				
		Marks/Ch				Drill Holes	_	Off-set							·
	_	Turning S	=		<u> </u>	Finish	\vdash	-	Calibration		-				
	Wave/Twist in Tube					Fit/Function		Out of Sequence							

109767

Page 2

Thursday, November 28, 2013 3:17:24 PM Item ID: D3265-043 Accept *N900040100* Setup Start **Revision ID:** Rib Assembly Item Name: Start Date: 11/28/2013 Start Qty: 1.00 **Cust Item ID:** Required Date: 12/5/2013 **Reg'd Qty:** 1.00 *1* **Customer:** Reference: Run **Process Plan:** Approvals: Date: **Tooling:** Date: Stop QC: SPC (Y/N): Date: Date: Sequence ID/ Operation Tool ID Set Up/ Tool # Plan Accept Reject Reject Work Center ID Description **Run Hours** Code Qty Qty Number Stamp 120 Identify as per dwg & Stock Location: WHOOV *120* 13-11-28 Packaging 0.00 Memo **Packaging**

130

QC21- Final Inspection - Work Order Release

0.00

130 QC

Memo

0.00

Quality Control

Rm 13/11/29.

Insp.

DQA:	Date:										TQ AC			
	WORK ORDER NON-CONFORMANCE / UPDATE												AEROSPACE	
QA Closed:			Date:							Wo	ork Order up	date only		
						DISPOSITION	DISPOSITION AGAINST DEPARTMENT/PROCESS							
Work Order:						F	1			_	• 1		, 	
						Rework			——	sstube	_	Water Jet	Engineering	
Part No	o. —					Scrap			~ —	nall Fab	!	d. Eng. Coor.	Quality	
NICD AL	_					Use-as-is		inern	~ ⊢	nishing	Kec/Stor	e/Packaging	Other	
NCR No	o				_	Suspected Unapproved]		Large Fab Com	nposite		Supplier	┙	
Root	T	1		1	Desci	ription of work order update	order update Initial Action				Sign &			
Cause	ł	Date	Step	Qty		or non-conformance	ŧ	ief Eng	Description		Date	Verification	QC Inspector	
Design	+			~~,			 							
Doc/Data		ĺ												
Equip/Tooling	1													
Handling/Pre														
Material														
Operator		Ì					Ì							
Offset/Setup														
Process														
Supplier														
Training	_		İ											
Transport	_										1			
Unapproved							<u></u>					*		
							FA	ULT CAT	regory					
Landing	_					General	_	1			1		7_	
-	-	ending			-	Bend	<u> </u>	4	Program		Outside Dim	<u> </u>	Pressure/Forced	
-	_		t Concer	itric	<u> </u>	BOM/Route	\vdash	Grain		<u> </u>	Over/Under		Set-up	
-	_	racks	l. /p:1	/\A1====	-	Broken/Damage/Defect	\vdash	Hardwa		ind	Part Incorred		Temperature/Cure Weld	
<u> </u>	_	•	k/Ripple	/wave	\vdash	Burrs	-	4	ion Incomplete/Unqualifi		Part Lost/Mi	ssing		
-	_	uffs ruching			\vdash	Contamination Countersink	\vdash	-	tions Incomplete/Unclear gned/off center	' 	Part Moved Positioned V	/rong	Wrong Stock Pulled	
	Crushing					Cut Too Short	-	Mislabe	=	-	Power Loss/		Other	
-	Heat Treat Inspection Strip in Tube					Drawing	-	Misrea		L	J. Ower 2033/		Total	
	_	iarks/Ch	-	, and	\vdash	Drill Holes	-	Off-set						
	_		equence			Finish	\vdash	4	Calibration					
	—	-	ist in Tub			Fit/Function		4	Sequence			·		

Required Date: 12/5/2013

Required Qty: 1.00

Thursday, November 28, 2013 3:17:22 PM

Work Order ID:

109767

Parent Item:

Comments:

D3265-043

Parent Item Name:

Rib Assembly

IPP REV:A 12.07.26 AS PER DWG REV.D DD VERF:EC

IPP REV:B 12.08.08 AS PER

864.9375

435.9375 478.38571

Start Date: 11/28/2013

Start Qty: 1.00


	DWG REV.E DD	VERF:EC						•					
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3759-1 Bushing		Manufactured	No			100	Each	157.0000	3 FR	3	359 	1}	
				Location		Loc Qty	<u>Lo</u>	c Code		INY	359 > 89 > a	/ ሚ / ጎ	
				WA004		157			یت	1971	07	ex }	
				102	073	1				<u> </u>			
				106	359	2					10		
					686	44				(CC 1	13-1	128
				` 107		28							
					591	78							
				108	412	4							
M304TS0.750W.065 \ 304SQ Tube 75x.75x.06	5.W	Purchased	No			100	f	1,779.2608	4.729	5_ 26_9.2_	2 -> -4	7,29)
~				Location		Loc Qty	Lo	c Code					7
				WA004		1779.260757					11		
				123	303	0.0000474				— (L [13	-11.	20

125513

m126538


m126922

DQA: Date:	Date:											
WORK ORDER NON-CONFORMANCE / UPDATE	AEROSPACE											
QA Closed: Date: Work Order update	only											
DISPOSITION AGAINST DEPARTMENT/PROC	AGAINST DEPARTMENT/PROCESS											
Work Order:	(star lat											
	ater Jet Engineering Quality											
Part No Scrap Machining Small Fab Prod. Eng Use-as-is Thermoforming Finishing Rec/Store/Pac	·											
	Supplier											
Juspected Onapproved Large Fab Composite S	мррист											
Root Description of work order update Initial Action Sign &												
	rification QC Inspector											
Design												
Doc/Data Doc/Data												
Equip/Tooling												
Handling/Pre												
Material Material												
Operator												
Offset/Setup												
Process												
Supplier												
Training												
Transport												
Unapproved												
FAULT CATEGORY												
Landing Gear General	<u> </u>											
Bending Bend Folio/Program Outside Dimension	├ ─┤											
Centre Not Concentric BOM/Route Grain Over/Under tolera												
Cracks Broken/Damage/Defect Hardware Part Incorrect	Temperature/Cure Weld											
Crimp/Kink/Ripple/Wave Burrs Inspection Incomplete/Unqualified Part Lost/Missing Cuffs Contamination Instructions Incomplete/Unclear Part Moved	Wrong Stock Pulled											
Crushing Countersink Misaligned/off center Positioned Wrong Heat Treat Cut Too Short Mislabeled Power Loss/Surge												
Inspection Strip in Tube Drawing Misread	Todici											
Marks/Chatter Drill Holes Off-set												
Turning Sequence Finish Out of Calibration												
Wave/Twist in Tube Fit/Function Out of Sequence												




•

DQA:			Date:										TO ACT		
						WORK ORDER NON	-CC	NFOF	RMANCE / UPI	DATE			AEROSPACE		
QA Closed:			Date:							W	ork Order up	date only			
Work Orde	or.					DISPOSITION									
Work Order.						Rework	1 i		Skid-tube	Crosstube	Water Jet Engineering				
Part N	Jn.					Scrap		1	Machining	Small Fab	Pro	Quality			
	٠٠.					Use-as-is	1 1		noforming	Finishing	_	e/Packaging	Other		
NCR N	No.					Suspected Unapproved	1			Composite	1	Supplier	1		
	•					'					-				
Root		Des			Desc	ription of work order update	1	nitial	Actio	on	Sign &				
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description		Date	Verification	QC Inspector		
Design						•									
Doc/Data			1												
Equip/Tooling			Ì				ł								
Handling/Pre															
Material															
Operator															
Offset/Setup															
Process							1								
Supplier			'												
Training															
Transport			ŀ		ļ										
Unapproved												- <u></u>	<u></u>		
							FA	ULT CAT	TEGORY						
Landi	ng (Gear				General		•		_	_		-		
		Bending				Bend	L	Folio/F	Program	_	Outside Dim		Pressure/Forced		
		Centre No	ot Concer	ntric		BOM/Route		Grain		_	Over/Under	tolerance	_Set-up		
		Cracks			_	Broken/Damage/Defect	<u> </u>	Hardwa	are	_	Part Incorre	├	Temperature/Cure		
	Crimp/Kink/Ripple/Wave					Burrs		Inspect	ion Incomplete/Unq	qualified	Part Lost/Mi	ssing	Weld		
	Cuffs					Contamination	L	i	tions Incomplete/Un	nclear	Part Moved	L	Wrong Stock Pulled		
	Crushing					Countersink	L	4	gned/off center		Positioned V	_	¬		
Heat Treat						Cut Too Short		Mislabe	el ed		Power Loss/	Surge	Other		
		Inspectio	n Strip in	Tube		Drawing		Misrea	d						
		Marks/Ch	natter			Drill Holes	L	Off-set				<u></u>			
		Turning S	Sequence			Finish		Out of	Calibration						
1	Wave/Twist in Tube					Fit/Function	1	Out of Sequence							



DQA:			Date:										TOACT		
						WORK ORDER NON-	-CC	ONFO	RMANCE / UPDATE				AEROSPACE		
QA Closed:			Date:							W	ork Order up	odate only			
						DISPOSITION			AGAINS						
Work Orde	er:					Danie ali	,		Child Arab a Connection		1	Water let] [
Don't N						Rework			Skid-tube Crosstub Machining Small Fa	-	l Dro	Water Jet d. Eng. Coor.	Engineering Quality		
Part N	10.				!	Scrap Use-as-is			Machining Small Fa		4	re/Packaging	Other		
NCR N	In					Suspected Unapproved		1116111	Large Fab Composi	~ 	1 1160/3101	Supplier			
NCK I	٠٠.					Suspected Onapproved			composi	···	1	Supplie	J LJ.		
Root					Desc	ription of work order update		nitial	Action		Sign &				
Cause		Date	Step	Qty		or non-conformance	ı	ief Eng	ĺ		Date	Verification	QC Inspector		
Design			,												
Doc/Data															
Equip/Tooling															
Handling/Pre							1								
Material															
Operator	·														
Offset/Setup						,									
Process						,									
Supplier									ļ						
Training						•					1				
Transport		j					ł								
Unapproved				<u> </u>	<u> </u>		<u> </u>				<u> </u>		1		
							FA	ULT CA	TEGORY			4			
Landii	ng (1				General]	N]	:	7p		
		Bending			-	Bend BOM/Boute	\vdash	Grain	Program	-	Outside Dim Over/Under		Pressure/Forced Set-up		
		Centre No	ot Concer	TUTIC	-	BOM/Route Broken/Damage/Defect	\vdash	Hardwa	200	\vdash	Part Incorre		Temperature/Cure		
		Cracks Crimp/Kir	nk/Dinnla	/\Mayo	-	Burrs	\vdash	4	ion Incomplete/Unqualified	H	Part Lost/Mi		Weld		
		Cuffs	IK) KIPPIE	y wave	-	Contamination		1 '	tions Incomplete/Unclear	\vdash	Part Moved	· · · -	Wrong Stock Pulled		
	-	Crushing			-	Countersink	\vdash	-	gned/off center		Positioned V				
	Heat Treat					Cut Too Short	\vdash	Mislabe			Power Loss/		Other		
		Inspectio		Tube		Drawing	\vdash	Misrea		<u> </u>	· · · · · · · · · · · · · · · · · ·	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
		Marks/Ch	•		-	Drill Holes		Off-set				 			
		Turning S				Finish		4	Calibration						
		Wave/Tw	ist in Tub	oe		Fit/Function		Out of Sequence							



DQA:			Date:			_										
						WORK ORDER NON-	-CC	ONFO	RMANCE / UPD				AEROSPACE			
QA Closed:			Date:							Wo	ork Order up	date only				
Work Ord	≥r·					DISPOSITION			AGAINST DEPARTMENT/PROCESS							
						Rework			Skid-tube 0	Crosstube		Water Jet	Engineering			
Part i	No.					Scrap				Small Fab	Pro	d. Eng. Coor.	Quality			
	•					Use-as-is		Thern	noforming	Finishing	Rec/Stor	e/Packaging	Other			
NCR I	۷o.					Suspected Unapproved		Large Fab Composite				Supplier				
			T	1	D		لــ	:4: !	A -+:		Cian 0					
Root		Data	Chan		Desc	ription of work order update		nitial	Action		Sign & Date	Verification	QC Inspector			
Cause		Date	Step	Qty		or non-conformance	Cn	ief Eng	Descripti	ION	Date	verification	QC Hispector			
Design	_		1													
Doc/Data Equip/Tooling	\vdash						ļ		,	•						
Handling/Pre			}				1									
Material	H								·							
Operator				ļ		•										
Offset/Setup	\vdash															
Process	\vdash															
Supplier			·													
Training					· ·											
Transport						•										
Unapproved	Г						l					-				
			<u> </u>				FA	ULT CA	regory							
Landi	ng (Gear				General		_			_		·			
		Bending				Bend		Folio/F	rogram	<u> </u>	Outside Dim	ensions	Pressure/Forced			
		Centre N	ot Conce	ntric		BOM/Route	L	Grain			Over/Under	tolerance	Set-up			
		Cracks			L	Broken/Damage/Defect		Hardwa	ire		Part Incorred	:i	Temperature/Cure			
		Crimp/Ki	nk/Ripple	e/Wave	L	Burrs		Inspect	ion Incomplete/Unqu	alified	Part Lost/Mi	ssing	Weld			
		Cuffs				Contamination		Instruct	tions Incomplete/Uncl	lear	Part Moved	L	Wrong Stock Pulled			
		Crushing				Countersink		Misali	ned/off center		Positioned V					
		Heat Tre	at			Cut Too Short		Mislabe			Power Loss/	Surge	Other			
	L	Inspectio	on Strip in	Tube	L	Drawing	_	Misrea								
	L	Marks/Cl	hatter		L	Drill Holes		Off-set								
	L	-	Sequence			Finish		-	Calibration			·	·			
		Wave/Tv	vist in Tul	be		Fit/Function	Ŀ	Out of	Sequence	· ·		· · · · · · · · · · · · · · · · · · ·				
"H:/FORMS/QL	ality	Assurance\	approved Q	A/NCRW	O RevH											